

TECHNICAL SERVICE BULLETIN

To: All Dealer Service Departments

From: Minuteman Technical Support

Date: 11/27/2018

Subject: TSB for - New brush motor shaft and key for brush hub on Max Ride 20 rider scrubbers

Reason for Change

Strengthens the contact between the brush shaft and drive hub.

Improvement

Increases the life of the 172510 brush motor hub.


Models Affected

MR20DQP, MR20DQPG, MR20DSQP, MR20DSQPG, A-MR20DQP, A-MR20DQPG and A-MR20DSQP, A-MR20DSQP.


Reference Kit Instructions – Please order the new style shaft and key, when replacing the old style 245107 shaft or 172510 hub.

New brush shaft part number 246947

New key for shaft part number 246946. (not shown)



Old style shaft part number 245107



New style shaft part number 246947

■ Informational Only