

PRODUCT UPDATE

To: [Distributor/Customer]

From: Minuteman Technical Support

Date: 1/26/23

Subject: TSB for E14 Recovery Tank (part #2655-0114-0) and Recovery Lid (part #2655-0115-0)

Reason for Change

Improvement for ease of installation and removal of Recovery Lid assembly.

Improvement

Both the Recovery Tank and Lid assembly have been remodeled from a straight fit design to a 45-degree angle design.

Models/Serial Numbers Affected

All E14 (E14BQP/E14115)

(serial numbers affected 22261344, 22261345, 22261346, 22261347, 22261348, 22261414, 22261415, 22261416, 22261417 and 22261418)

Special Instructions

Old style lid will not fit new style Recovery Tank. When replacing either assembly, both need to be replaced as a whole (together)







Informational Only For Purchase Warranty

For further assistance, questions, or comments contact Technical Support at 800-982-7141 (USA)