

DATE: December 11, 2006

TO: All Minuteman Dealers And Service Centers

FROM: Technical Support Department

RE: Port A Scrub 14 (Model M14110)

There has been a change on the Vacuum Fuse and Brush Circuit Breaker on the Port A Scrub 14, Model M14110.

The Vacuum Fuse part number 932106 has been upgraded from a 6.3 amp fuse to a 10 amp.

The Brush Circuit Breaker part number 925332 has been upgraded from a 6 amp to a 9 amp.

