

## TECHNICAL SERVICE BULLETIN

---

To: All Powerboss Dealers- Sales and Service

From: PowerBoss Technical Support

Date: 11-1-19

Subject: TSB for ECN 150687 Adding Shroud, new Motor & Broom change to the Atlas.

---

### **Reason for Change**

Dealers requested and we listened for improved finished appearance.

Increased durability and reliability (side brush and hydraulic brush motor) that will decrease the cost of ownership.

Curb broom motor is now the same as used on the SW9X (3316897) along with the associated gimbal plate and hardware in order to accomplish this change.

### **Improvement**

Atlas now uses the same side broom as the SW9X AND SW10X

This cannot be retrofitted to older units.

---

### **Models/Serial Numbers Affected**

ALL ATLAS UNITS- Both Single and Dual curb brooms

Beginning at serial number 19PB1438 August 1<sup>st</sup>, 2019

Brooms being use on the Atlas now:

3339964 26" Poly- Standard Broom

3339963 26" Nylon



Informational Only    For Purchase    Warranty    Product Improvement

**For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)**