

TECHNICAL SERVICE BULLETIN

To: [Distributor/Customer]

From: PowerBoss Technical Support

Date: 1/31/2023

Subject: TSB Flashing All AO1 controllers in the Scrubmaster Series Scrubbers

Reason for Change

With the new 2023 Hako Diagnostic Software using the Powerboss serial number with letters in the body, the software does not recognize the number.

Example: PSM3332C00352

Improvement

This serial number will need to be converted to the Hako Serial number.


Example: 717746000352

This bulletin will explain how to accomplish this. It will also be posted on the Powerboss website inside the Hako Software folder.

Models/Serial Numbers Affected

B120R, B175R, B260R and B400RH

Reference Instructions – For Installation Procedure See Below:



HAKO CONVERTED SERIAL



POWERBOSS SERIAL

HAKO CONVERTED SERIAL



YEAR LETTER
TO
NUMBER DESIGNATION

N = 2018

0 = 2019

P = 2020

Q = 2021

R = 2022

S = 2023

T = 2024

POWERBOSS SERIAL NUMBER: QSM3346CSB00261

Understanding the 2 Serial Numbers

Q = LAST DIGIT OF THE YEAR OF MANUFACTURE SM3346 = MACHINE VARIANT 0026 = MACHINE SERIAL 1 = MONTH OF MANUAFACTURE

HAKO SERIAL NUMBER CONVERTED 781036100261

MACHINE VARIANTS

POWERBOSS SERIAL: HAKO SERIAL:

QSM3346CSB00261 781036100261

B120R:

SM3032D 717740

SM3532D 717742

717746 SM3332C

SM4246D 718016

MACHINE VARIANTS

POWERBOSS SERIAL:

Q\$M3346C\$B00261

B175R:

\$M3546D

\$M3346C\$

\$M3346C\$

\$M3346C\$

\$M3346C\$B

(WILL HAVE TO CONFIGURE)

| Informational Only | For Purchase | Warranty | Product Improvement