

TECHNICAL SERVICE BULLETIN

To: Dealers and Service Technicians

From: Minuteman Technical Support

Date: 02/07/2018

Subject: K-2630STP Solution Tank Patch Kit is now available.

Reason for Change

Solution tanks can crack when tilting the recovery tank to the side, when it is full of water. The kit will repair cracks in the solution tanks in the area shown below without replacing the tank.

Models/Serial Numbers Affected

Models E24, E26, E28, E30, E33XL, E2830, E3030 and E3330

For all 19, 24, 30 gallon walk behind scrubber/dryers as needed.

Note: For models that the tank is still under warranty. The patch kit may be used for warranty repairs. The patch would be covered by warranty for the remainder of the original tank warranty. Labor coverage will not be extended past the original warranty terms.





▼ Informational Only ▼ For Purchase

Please contact Technical Support with any questions. Phone 1-800-323-9420 Option 2