

TECHNICAL SERVICE BULLETIN

To: [Distributor/Customer]

From: Minuteman Technical Support

Date: 4/2/2019

Subject: TSB for E14 Belt Pulley – Vibration of Brush or Pad Driver

Reason for Change

The brush or pad driver on some machines may vibrate and shake the machine while operating.

Improvement

The belt pulley has been redesigned to eliminate vibration between brush/pad driver and the hub.

Models/Serial Numbers Affected

E14BQP, E14115 and E14220 - Machines produced before October 1, 2018.

Machines with serial numbers before 1810XXXX may be a candidate for this issue, if vibration is occurring. .

Reference - Instructions – Replace part number 4435-0000-0 Belt Pulley



Belt Pulley with Hub

Original style pulley

New revised pulley



Informational Only