

TECHNICAL SERVICE BULLETIN

To: All Powerboss Service and Parts dealers

From: PowerBoss Technical Support

Date: 4-6-2020

Subject: Admiral Series drive wheel PN: 00910150 shipped without gear oil

This bulletin is to advise and let you know the drive wheel assembly on the Admiral Series units are shipped without oil.

You will need to fill them via the port on top with .7 gallons of SAE-90 gear oil prior to installing or using a new replacement drive wheel.

This is for aftermarket replacement only. New units are shipped with oil in the gear cases.

Models/Serial Numbers Affected

Admiral 38, 40 and 48 units with drive wheel part number 00910150

This is for informational purposes only.



Informational Only For Purchase Warranty Product Improvement