

## TECHNICAL SERVICE BULLETIN

---

**To:** POWERBOSS DEALERS and SERVICE DEPARTMENTS

**From:** PowerBoss Technical Support

**Date:** 8/31/2010

**Subject:** TSB FOR ECN# 10641- KIT/FLD RADIATOR MOUNT P/N 3336801

---

**Reason for Change**

THIS WILL REDUCE THE FLEXING AND EXTEND THE SERVICE LIFE OF THE RADIATOR.

**Improvement**


THE NEW BRACE DESIGN WILL ADD RUBBER ISOLATORS WHICH WILL LIMIT THE FLEXING OF THE RADIATOR.

---

**Models/Serial Numbers Affected**

ALL COMMANDER AND MONITOR MODELS WITH GM 1.6Ltr ENGINES

**Reference Kit Instructions** –THE KIT PART NUMBER **3336801** WILL ADD NEW BRACKETS AND RUBBER ISOLATORS. THE RADIATOR IS INCLUDED IN THE KIT.



**For further assistance, questions, or comments contact Technical Support at 800-982-7141 (USA)**