

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Centers

From: PowerBoss Technical Support

Date: 3-1-19

Subject: TSB for ECN 150553 (SW10X brake return spring)

Reason for Change

Existing spring may not allow arm to fully return when used.

Improvement

Replace old spring (3334098) with new spring (3301522)

Models/Serial Numbers Affected

SW10XLPG, SW10XGAS, SW10XDSL, beginning serial number 19PB****

Reference Kit Instructions

Replace as needed

Informational Only For Purchase Warranty Product Improvement

For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)