

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Managers

From: PowerBoss Technical Support

Date: 1/22/2016

Subject: TSB for 12813 - Squeegee Inner Band Retaining Strap

Reason for Change

It has been noted in some cases the front (inner) squeegee band comes loose and falls off.

Improvement

Add a retaining strap to squeegee assembly to assist holding the band in place.

Models/Serial Numbers Affected

Nautilus Units (All Versions) Prior to July 1, 2015

Reference Kit Instructions - For Installation Procedure

Order one (1) kit: K-730764 per unit if needed

□ Informational Only □ For Purchase ⊠ Warranty

For further assistance, questions, or comments contact Technical Support at 800-982-7141 (USA)