

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Managers

From: Powerboss Technical Support

Date: 10-1-2013

Subject: TSB for PWR-12078 BROOM LIFT HANDLES

Reason for Change: OLD BROOM LIFT HANDLES ARE NO LONGER AVAILABLE: 3334987 & 3335001

Improvement: WHEN REPLACING THE OLD LIFT HANDLES WITH NEW YOU WILL ALSO NEED TO ORDER THE NEW GRIPS FOR EACH HANDLE ORDERED (600264)

Models/Serial Numbers Affected

ALL 9X AND 10X SERIES SWEEPERS BEGINNING SERIAL NUMBER: 19874043

Reference Kit Instructions

Informational Only For Purchase Warranty Product Improvement

3334987 REPLACED BY: 3338296 AND (1) GRIP 600264

3335001 REPLACED BY: 3338297 AND (1) GRIP 600264

For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)