

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Managers

From: PowerBoss Technical Support

Date: 12/17/2013

Subject: TSB for PWR-12385 HELAC ROTARY ACTUATOR BEING REPLACED

Reason for Change

Quality enhancement: The Helac rotary actuator is now being replaced by a steering cylinder on current production units.

Improvement

Easier to replace and less labor intensive

NOTE: This new cylinder is NOT a direct replacement for those units that have Helac rotary actuators.

Models/Serial Numbers Affected

ARMADILLO SW-9X SERIES UNITS BEGINNING SN: 20121103

ZAOH AM9D-II UNITS BEGINNING SN: 13100001

NEW STEERING CYLINDER SPARE PART NUMBER: 3345027 (SW-9X ONLY)
3307311 (AM9D-II ONLY)



HELAC

STEERING CYLINDER



Informational Only

For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)