

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Managers

From: PowerBoss Technical Support

Date: 2/19/2016


Subject: TSB for ECN MIN-13050 – Curb Broom Actuator and Cable

Reason for Change

Product improvement. Stronger actuator and spring added to protect it from minor impacts while in the retracted position.

Improvement Description

Should a side broom actuator fail, the kit, K-661145, should be ordered to replace the old actuator (3318886).



Models/Serial Numbers Affected

All SW6X and AM7D-III – Beginning serial number: 15011536 (AUG 2015)

Reference Kit Instructions – For Installation Procedure

K-661145 - Side Broom lift actuator and cable replacement kit.

Informational Only For Purchase Warranty

For further assistance, questions, or comments contact Technical Support at 800-982-7141 (USA)