

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Managers

From: Powerboss Technical Support

Date: 10-1-2013

Subject: TSB for PWR-11726, 12120 & 12151

Reason for Change: OLD SPOOL VALVES ARE NO LONGER AVAILABLE: 3307433, 3300357, & 3317238

Improvement: WHEN REPLACING THE OLD SPOOL VALVE WITH NEW, IT'S NOT A DIRECT REPLACEMENT. THE SUBASSEMBLY THAT INCLUDES THE NEW VALVE WILL HAVE TO BE ORDERED ALONG WITH THE NEW GRIPS AND HOSES WHERE NOTED BELOW.

Models/Serial Numbers Affected

ALL 9X, 10X SERIES SWEEPERS BEGINNING SERIAL NUMBER: 20001073

ALL C82, M82, T82, C90, M90 AND T90 UNITS BEGINNING SERIAL NUMBER: 19968063

Reference Kit Instructions

Informational Only For Purchase Warranty Product Improvement

3307433 USE ASSEMBLY 3338602 ON 9X & 10X
WILL ALSO NEED (3) 600264 HANDLE GRIPS

3300357 USE ASSEMBLY 3345011 ON T82 & T90'S
WILL ALSO NEED (3) 600264 HANDLE GRIPS

3300357 USE ASSEMBLY 3345012 ON C82, C90, M82 AND M90
WILL ALSO NEED (1) 600264 HANDLE GRIP

3317238 USE ASSEMBLY 3344572 IMPELLER SPOOL AND:

ON THE 82 SERIES UNIT WILL NEED (1) 600264 HANDLE GRIP, (1) 3343691 HOSE AND (1) 3342897 HOSE

ON THE 90 SERIES UNIT WILL NEED (1) 600264 HANDLE GRIP, (1) 3343691 HOSE AND (1) 3342896 HOSE

For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)