

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Managers
From: Powerboss Technical Support
Date: 3/28/2013
Subject: TSB for ECN 11973 - New Kubota WG1605 LP Engine
Reason for Change
GM 1.6 LP and Gas engines are being discontinued.
<u>Improvement</u>
Increased reliability and improved engine dealer network (Kubota)
Models/Serial Numbers Affected
Armadillo 9X, 10X, Commander, Monitor, and Core Series units
Current 9X (LP) beginning SN: 19816033, other units to follow in near future.
☑ Informational Only ☐ For Purchase ☐ Warranty

For further assistance, questions, or comments contact Technical Support at 800-982-7141 (USA)