

NEW IMPROVED MAIN BROOMS & HUB

Dear Valued PowerBoss Dealers,

As of January 1st, 2019 we have implemented a new improved main broom hub design and patent pending proprietary main brooms for all Armadillo Sweepers, Atlas Sweepers and Nautilus Scrubbers. This update comes packed with some pretty awesome advantages.

1. The new hub is splined in such a way that it makes replacing brooms in the field much easier and faster.
2. The new brooms come equipped with a wear indicator.
 1. These new brooms can be identified with a "-PH" item number suffix
3. These new brooms are proprietary patent pending which will help our dealers take control over their aftermarket broom business.
4. For machines with serial numbers beginning with "19PB" you will only need to stock one hub (item 731304-1) as the same hub is used on all Armadillo, Atlas & Nautilus machines.

We want to make it as easy as possible for you to manage this change so you have a few options as follows:

1. You can choose to order and stock both the old style and new style brooms.
2. You can update the hubs on machines in the field so that they will accept the new brooms. In this case you can submit a warranty claim and we will cover the cost of the hub only.
 1. ***This would be your fastest track to capitalizing on these new proprietary brooms and your aftermarket broom business.***
 2. For this case you will need 1 each of item 731304-1 hub per broom
3. You can change the inserts on your stock of old style brooms so they can be adapted to machines with new hubs. In this case you will need 2 each of item 731330 insert per broom.



OLD STYLE HUB
(items 3301050P, 3301051
or 600337)



NEW STYLE HUB
Item 731304-1
Use on all Armadillo,
Atlas & Nautilus
beginning with serial #
19PB



NEW BROOM INSERT
Item 731330

If you have any questions please contact Chris Failla at failla.c@minutemanintl.com.

Sincerely,

The PowerBoss Team

Informational Only For Purchase Warranty Product Improvement

For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)