

TECHNICAL SERVICE BULLETIN

To: All Dealers and Service Centers

From: Power Boss Technical Support

Date: 5/20/2010

Subject: TSB for ECN # HA09-0507 - New Drive Hub Kit Part Number K-E1720HUB

Reason for Change New and improved

<u>Models/Serial Numbers Affected</u>- All Phoenix 20 and Phoenix 22 with disk brush decks. The disk models will be equipped with the new hubs from the factory. They will be installed on machines with serial numbers starting with the letter "E".

<u>Instructions</u> – The original style disk brushes that used the black tri-lobe hub system will no longer be available. When ordering replacement brushes or pad driver listed below, the drive hub kit **(K-E1720HUB)** will be needed.

<u>Note</u> - Power Boss will warranty the first replacement hub per machine, when a warranty claim has been filed.



New Style Hub



New style clutch plate***

New style brushes and pad holders will be required for this change. They will be sold separately. See below Brushes and Pad Holders

Phoenix 20 and 22 (Disk Deck)	Description
172520-1	Nylon Brush
172520-2	Pad Driver
172520-3	Nylo-Grit 80 Grit
172520-6	Scrub Grit 120 Grit

***Clutch plates are not sold separately Clutch plates are included with brushes and pad holders

For further assistance, questions, or comments contact Technical Support at 800-982-7141 (USA)

175 Anderson Street · Aberdeen, North Carolina 28315 USA Phone: 800-323-9420 Fax 630-627-1130 www.powerboss.com