

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Managers

From: Powerboss Technical Support

Date: 10-1-2013

Subject: ATLAS USERS MANUAL (Rev. A 6/11) CORRECTION, pg 53

Reason for Change

TO CORRECT THE HYDRAULIC OIL SPECIFIED IN THE ATLAS SWEEPER USERS MANUAL

Improvement

INFORMATION ONLY

Models/Serial Numbers Affected

ALL ATLAS USER MANUALS

Reference Kit Instructions – NONE

Informational Only For Purchase Warranty Product Improvement

ORIGINAL: THE RECOMMENDED HYDRAULIC FLUID WAS 15w-40w (15W40).

 CAUTION
DO NOT OVERFILL! DO NOT USE TRANSMISSION FLUID PowerBoss, Inc. recommends 15w-40w motor oil. We Currently use EXXON XD-3

CORRECTION: THE RECOMMENDED HYDRAULIC FLUID IS DTE 10 EXCEL 68 HYDRAULIC OIL OR EQUIVALENT ONLY.

 CAUTION
DO NOT OVERFILL HYDRAULIC RESEVOIR TANK! DO NOT USE TRANSMISSION FLUID! PowerBoss, Inc. recommends using: DTE 10 EXCEL 68 Hydraulic oil or equivalent only.

ALL OTHER POWERBOSS UNITS STILL USE THE 15W40 MOTOR OIL FOR THEIR HYDARULIC FLUID.

For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)