

TECHNICAL SERVICE BULLETIN

To: [Distributor/Customer]

From: PowerBoss Technical Support

Date: 4/24/23

Subject: TSB for 730939 Side Scrub Squeegee for Nautilus/HD equipped with Side Scrub Option

Reason for Change


To accommodate a new style side scrub brush.

Improvement

The side squeegee has additional holes to accommodate the new style brush

Models/Serial Numbers Affected - Effective on serial number 23PB1371

Product Improvement – Not for warranty purposes



Old Style Scrub Brush



New Style Scrub Brush

For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)